

FIG. 1
(PRIOR ART)




FIG. 4A




FIG. 5




FIG. 6 is a schematic diagram of a mechanical assembly in a cross-sectional view. The assembly includes a main body 1 with a longitudinal slot 2. Inside the slot, there is a component 10 with a series of small protrusions 141. A curved arrow indicates a rotational movement of the assembly around a pivot point 4. Various sub-components are labeled with reference numerals: 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200. A dashed line 3 indicates a specific feature or boundary.